



**European Motors Inc**  
 6401 West Park Boulevard  
 Plano, TX 75093  
 (972) 473-5793  
 service@europeanmotorsusa.com  
 http://www.europeanmotorsusa.com

**Invoice for RO #564**

Service Advisor: --  
 Posted Date: 02/06/24 at 02:58 PM CST  
 Client: European Motors Inc  
 Vehicle: 2019 Land Rover Range Rover Sport HSE

European Motors Inc 6401 West Park Boulevard Plano, TX 75093 Phone: (972) 473-9400 Email: iman@europeanmotorsusa.com	<b>2019 Land Rover Range Rover Sport HSE</b> <b>3.0L 6Cyl GAS Supercharged</b> VIN: SALWR2RV2KA827952 License: N/A Color: White Odometer In: 79182 / Out: 79182	<b>RO #564</b> Key Tag: 127 Time-In: 02/03/24 at 03:38 PM CST Save Parts: No
--	--	---

**Client concerns:**

- Vehicle Check

1 - Remove & Replace Brake Pads				
<i>Labor:</i>	Remove & Replace Front Brake Pads	1.20 hrs	\$149.99	\$179.99
	Remove & Replace Rear Brake Pads	1.50 hrs	\$149.99	\$224.99
<i>Parts:</i>	Disc Brake Pad Set - Front	1	\$299.50	\$299.50
	Disc Brake Pad Set - Rear - Incl.Pad Clips	1	\$206.93	\$206.93
✓ Approved on 02/05/24 at 10:25 AM CST				<b>\$911.41</b>

2 - Remove & Replace Battery				
<i>Labor:</i>	Remove & Replace Battery Primary Battery	0.40 hrs	\$149.99	\$60.00
<i>Part:</i>	Primary Battery	1	\$339.99	\$339.99
✓ Approved on 02/05/24 at 10:25 AM CST				<b>\$399.99</b>

3 - Remove & Replace Front Rotors				
<i>Labor:</i>	Remove & Replace Front Rotors	1.75 hrs	\$149.99	\$262.48
<i>Part:</i>	Disc Brake Rotor - Front	2	\$243.98	\$487.96
✓ Approved on 02/06/24 at 05:57 PM CST				<b>\$750.44</b>

**Total Repair Order & Signature:**

X  
 -----

Total Labor: \$727.46  
 Total Parts: \$1,334.38  
 Total Fees: \$0.00  
**Subtotal: \$2,061.84**  
**Grand Total: \$2,061.84**  
**BALANCE DUE: \$2,061.84**