



European Motors Inc
 6401 West Park Boulevard
 Plano, TX 75093
 (972) 473-5793
 service@europeanmotorsusa.com
 http://www.europeanmotorsusa.com

RO #564

Service Advisor: --

Date Created: 02/03/24 at 03:38 PM CST

Client: European Motors Inc

Vehicle: 2019 Land Rover Range Rover Sport HSE

2019 Land Rover Range Rover Sport HSE 3.0L 6Cyl GAS Supercharged VIN: SALWR2RV2KA827952 License: N/A Color: White Odometer In: 79182 / Out: 79182	RO #564 Save Parts: No
---	---------------------------

Client concerns:

- Vehicle Check

Inspection Rating Key:

Checked & Okay Requires Attention Soon Requires Immediate Attention Not Applicable

18 Point Inspection		TECH: GERMAN AVILES
18 Point Inspection		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> All lights	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Horn	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Engine Oil	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Belts and Hoses	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Brakes Visual	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Cooling System	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Wiper Blades	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Air Filters	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Alignment	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Exhaust	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fluids	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Axle Boots	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Steering	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Suspension	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Body Damage	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transmission	Finding:	



Tire Pressure

Finding:



Battery (if Accessible)

Finding: