



European Motors Inc
 6401 West Park Boulevard
 Plano, TX 75093
 (972) 473-5793
 service@europeanmotorsusa.com
 http://www.europeanmotorsusa.com

RO #689

Service Advisor: --

Posted Date: 06/10/24 at 06:10 PM CDT

Client: European Motors Inc

Vehicle: 2018 BMW X5 xDrive40e

2018 BMW X5 xDrive40e 2.0L 4Cyl PLUG-IN HYBRID EV-GAS (PHEV) N20B20A Turbocharged VIN: 5UXKT0C58J0W03429 License: N/A Color: Silver Odometer In: 117040 / Out: 117040	RO #689 Save Parts: No
--	---------------------------

Client concerns:

- CEL

Inspection Rating Key:

Checked & Okay	Requires Attention Soon	Requires Immediate Attention	Not Applicable
----------------	-------------------------	------------------------------	----------------

18 Point Inspection	TECH: N/A
18 Point Inspection	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> All lights	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Horn	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Engine Oil	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Belts and Hoses	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Brakes Visual	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Cooling System	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Wiper Blades	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Air Filters	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Alignment	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Exhaust	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fluids	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Axle Boots	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Steering	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Suspension	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Body Damage	Finding:

<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transmission	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Tire Pressure	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Battery (if Accessible)	Finding: