



European Motors Inc
 6401 West Park Boulevard
 Plano, TX 75093
 (972) 473-5793
 service@europeanmotorsusa.com
 http://www.europeanmotorsusa.com

RO #556

Service Advisor: --

Posted Date: 02/03/24 at 11:08 AM CST

Client: European Motors Inc

Vehicle: 2019 Mercedes-Benz GLC43 AMG 4Matic

2019 Mercedes-Benz GLC43 AMG 4Matic 3.0L 6Cyl GAS 276.823 Turbocharged VIN: WDC0G6EB8KF524323 License: N/A Color: Black Odometer In: 61054 / Out: 61054	RO #556 Save Parts: No
---	---------------------------

Client concerns:

- Vehicle Check

Inspection Rating Key:

	Checked & Okay		Requires Attention Soon		Requires Immediate Attention		Not Applicable
--	----------------	--	-------------------------	--	------------------------------	--	----------------

18 Point Inspection		TECH: N/A
18 Point Inspection		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	All lights	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Horn	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Engine Oil	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Belts and Hoses	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Brakes Visual	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Cooling System	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Wiper Blades	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Air Filters	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Alignment	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Exhaust	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Fluids	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Axle Boots	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Steering	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Suspension	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Body Damage	Finding:

<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transmission	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Tire Pressure	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Battery (if Accessible)	Finding: