



**European Motors Inc**  
 6401 West Park Boulevard  
 Plano, TX 75093  
 (972) 473-5793  
 service@europeanmotorsusa.com  
 http://www.europeanmotorsusa.com

**RO #606**

Service Advisor: --

Date Created: 02/09/24 at 10:20 AM CST

Client: European Motors Inc

Vehicle: 2019 Ford F-150 XLT

2019 Ford F-150 XLT 3.5L 6Cyl GAS Turbocharged VIN: 1FTEW1E46KFD14046 License: N/A Color: White Odometer In: 89746 / Out: 89746	RO #606 Save Parts: No
---	---------------------------

**Client concerns:**

- Vehicle Check

**Inspection Rating Key:**

Checked & Okay        Requires Attention Soon        Requires Immediate Attention        Not Applicable
---

18 Point Inspection		TECH: N/A
18 Point Inspection		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> All lights	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Horn	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Engine Oil	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Belts and Hoses	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Brakes Visual	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Cooling System	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Wiper Blades	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Air Filters	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Alignment	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Exhaust	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fluids	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Axle Boots	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Steering	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Suspension	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Body Damage	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transmission	Finding:	



Tire Pressure

Finding:



Battery (if Accessible)

Finding: