



European Motors Inc
 6401 West Park Boulevard
 Plano, TX 75093
 (972) 473-5793
 service@europeanmotorsusa.com
 http://www.europeanmotorsusa.com

RO #706

Service Advisor: --

Posted Date: 06/26/24 at 04:12 PM CDT

Client: European Motors Inc

Vehicle: 2010 Lexus IS350 Base

2010 Lexus IS350 Base 3.5L 6Cyl GAS 2GR-FSE Naturally Aspirated VIN: JTHFE2C28A2502005 License: N/A Color: Red Odometer In: 102624 / Out: 102624	RO #706 Save Parts: No
--	---------------------------

Client concerns:

- vehicle check

Inspection Rating Key:

Checked & Okay Requires Attention Soon Requires Immediate Attention Not Applicable

18 Point Inspection		TECH: N/A
18 Point Inspection		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> All lights	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Horn	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Engine Oil	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Belts and Hoses	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Brakes Visual	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Cooling System	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Wiper Blades	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Air Filters	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Alignment	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Exhaust	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fluids	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Axle Boots	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Steering	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Suspension	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Body Damage	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transmission	Finding:	

Tire Pressure

Finding:

Battery (if Accessible)

Finding: