



European Motors Inc
 6401 West Park Boulevard
 Plano, TX 75093
 (972) 473-5793
 service@europeanmotorsusa.com
 http://www.europeanmotorsusa.com

RO #766

Service Advisor: --

Posted Date: 07/02/24 at 03:19 PM CDT

Client: European Motors Inc

Vehicle: 2020 Lexus IS300 F Sport

2020 Lexus IS300 F Sport 2.0L 4Cyl GAS 8AR-FTS Turbocharged VIN: JTHGA1D24L5102484 License: N/A Color: Grey Odometer In: 79567 / Out: 79567	RO #766 Save Parts: No
---	---------------------------

Client concerns:

- vehicle check

Inspection Rating Key:

Checked & Okay Requires Attention Soon Requires Immediate Attention Not Applicable

18 Point Inspection		TECH: N/A
18 Point Inspection		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> All lights	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Horn	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Engine Oil	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Belts and Hoses	Finding:	
<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Brakes Visual	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Cooling System	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Wiper Blades	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Air Filters	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Alignment	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Exhaust	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fluids	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Axle Boots	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Steering	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Suspension	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Body Damage	Finding:	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transmission	Finding:	

Tire Pressure

Finding:

Battery (if Accessible)

Finding: