



European Motors Inc
 6401 West Park Boulevard
 Plano, TX 75093
 (972) 473-9443
 service@europeanmotorsusa.com
 http://www.europeanmotorsusa.com

RO #682

Service Advisor: Iman Fooman
Posted Date: 07/19/24 at 01:18 PM CDT
Client: European Motors Inc
Vehicle: 2018 BMW 330e Base

2018 BMW 330e Base 2.0L 4Cyl PLUG-IN HYBRID EV-GAS (PHEV) B48A20M0 Turbocharged VIN: WBA8E1C58JA171606 License: N/A Color: Black Odometer In: 65371 / Out: 65371	RO #682 Save Parts: No
---	---------------------------

Client concerns:

- vehicle check

Inspection Rating Key:

	Checked & Okay		Requires Attention Soon		Requires Immediate Attention		Not Applicable
--	----------------	--	-------------------------	--	------------------------------	--	----------------

18 Point Inspection		TECH: N/A
	18 Point Inspection	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	All lights	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Horn	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Engine Oil	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Belts and Hoses	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Brakes Visual	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Cooling System	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Wiper Blades	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Air Filters	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Alignment	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Exhaust	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Fluids	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Axle Boots	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Steering	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Suspension	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Body Damage	Finding:

<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transmission	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Tire Pressure	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Battery (if Accessible)	Finding: