



**European Motors Inc**  
 6401 West Park Boulevard  
 Plano, TX 75093  
 (972) 473-9443  
 service@europeanmotorsusa.com  
 http://www.europeanmotorsusa.com

**RO #778**

**Service Advisor:** Iman Fooman  
**Posted Date:** 08/01/24 at 10:51 AM CDT  
**Client:** European Motors Inc  
**Vehicle:** 2019 BMW M850i xDrive Base

2019 BMW M850i xDrive Base 4.4L 8Cyl GAS N63B44T3 <b>Turbocharged</b> VIN: WBABC4C56KBU95677 License: N/A Color: Black Odometer In: 68546 / Out: 68546	RO #778 Save Parts: No
---	---------------------------

**Client concerns:**

- vehicle check

**Inspection Rating Key:**

Checked & Okay        Requires Attention Soon        Requires Immediate Attention        Not Applicable
---

18 Point Inspection		TECH: N/A
18 Point Inspection		
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> All lights		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Horn		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Engine Oil		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Belts and Hoses		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Brakes Visual		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Cooling System		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Wiper Blades		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Air Filters		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Alignment		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Exhaust		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Fluids		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Axle Boots		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Steering		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Suspension		Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Body Damage		Finding:

<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transmission	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Tire Pressure	Finding:
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Battery (if Accessible)	Finding: